



## BERRY SURVEYING & ENGINEERING

335 Second Crown Point Road

Barrington, NH 03825

Phone: (603) 332-2863

Fax: (603) 335-4623

www.BerrySurveying.Com

Test Holes Completed for

2016-091 Oak Hill Road

By: Berry Surveying & Engineering

Witnessed by: Joe Berry

Dug by: Dan Ayer

October 4, 2016

### Test Hole #1

#### Depth (in.)

#### Description

0-3"	10YR 2/2, Very Dark Brown, Fine Sandy Loam, Granular, Friable, Duff
3-19"	10YR 3/6, Dark Yellowish Brown, Fine Sandy Loam, Granular, Friable, Few Fine Roots @ 7"
19-62"	2.5Y 3/3, Dark Olive Brown, Fine Sandy Loam, Fine Blocky, Firm in Hole, Friable in Hand, Redox @ 19", Con & Dep 10%
ESHWT @ 19"	
Terminated @ 62"	
No Ledge	
No GW	
Roots @ 17"	
PERC= 8MIN/IN	

### Test Hole #2

0-2"	10YR 2/2, Very Dark Brown Fine Sandy Loam, Granular, Friable, Duff
2-20"	10YR 4/6, Dark Yellowish Brown, Fine Sandy Loam, Granular, Friable
20-65"	2.5Y 5/2, Grayish Brown, Fine Sandy Loam, Fine-Med Blocky, Firm in Hole, Friable in Hand, Redox @ 20", Con & Dep 10%
Many Cobbles Throughout	

**RECEIVED**

DEC 14 2015

TOWN OF BARRINGTON, NH  
PLANNING BOARD

ESHWT @ 20"  
Terminated @ 65"  
No Ledge  
No GW  
Roots @ 25"  
PERC= 8MIN/IN

### Test Hole #3

0-3" 10YR 3/6, Dark Yellowish Brown, Fine Sandy Loam,  
Granular, Friable  
3-21" 10YR 4/6, Dark Yellowish Brown, Fine Sandy Loam,  
Granular, Friable, Few Roots @ 21"  
21-48" 2.5Y 5/2, Grayish Brown, Fine Sandy Loam, Fine Blocky,  
Firm in Hole, Friable in Hand, No Redox, Ledge or Boulder  
@ 48"  
Many Stones Throughout

ESHWT @ 21"  
Terminated @ 48"  
Ledge @ 48"  
No GW  
Roots @ 21"  
PERC= 8MIN/IN

### Test Hole #4

0-2" 10YR 2/2, Very Dark Brown, Fine Sandy Loam, Granular,  
Friable, Duff  
2-10" 10YR 3/6, Dark Yellowish Brown, Fine Sandy Loam,  
Granular, Friable  
10-24" 10YR 4/6, Dark Yellowish Brown, Fine Sand, Granular,  
Friable, Few Roots @ 24"  
24-53" 2.5Y 3/2, Very Dark Grayish Brown, Fine Sand, Fine Blocky,  
Firm in Hole, Friable in Hand, Redox @ 26", Con 5% No Dep

ESHWT @ 24"  
Terminated @ 53"  
Ledge @ 53"  
No GW  
Roots @ 24"  
PERC= 8MIN/IN

**RECEIVED**

DEC 14 2016

TOWN OF BARRINGTON, NH  
PLANNING BOARD



### BERRY SURVEYING & ENGINEERING

335 Second Crown Pt. Rd., Barrington, NH 03825  
(603) 332-2863 / (603) 335-4623 FAX  
[www.BerrySurveying.Com](http://www.BerrySurveying.Com)

### Test Hole #5

0-3" 10YR 3/6, Dark Yellowish Brown, Fine Sandy Loam,  
Granular, Friable  
3-19" 10YR 4/6, Dark Yellowish Brown, Fine Sandy Loam,  
Granular, Friable  
19-38" 2.5Y 5/2, Grayish Brown, Fine Sandy Loam, Fine Blocky,  
Firm in Hole, Friable in Hand, Few Roots @ 21", No Redox

ESHWT @ 19"  
Terminated @ 38"  
Ledge @ 38"  
No GW  
Roots @ 21"  
PERC= 8MIN/IN

### Test Hole #6

0-2" 10YR 2/2, Very Dark Brown, Fine Sandy Loam, Granular,  
Friable, Duff  
2-21" 10YR 4/6, Dark Yellowish Brown, Fine Sandy Loam,  
Granular, Friable, Few Roots @ 19"  
21-64" 2.5Y 6/2, Light Brownish Gray, Fine Sandy Loam, Fine  
Blocky, Somewhat Firm in Hole, Friable in Hand, Redox @  
23" Con & Dep 5%  
Few Stones

ESHWT @ 21"  
Terminated @ 64"  
No Ledge  
No GW  
Roots @ 19"  
PERC= 8MIN/IN

**RECEIVED**

DEC 14 2016

TOWN OF BARRINGTON, NH  
PLANNING BOARD



### BERRY SURVEYING & ENGINEERING

335 Second Crown Pt. Rd., Barrington, NH 03825  
(603) 332-2863 / (603) 335-4623 FAX  
[www.BerrySurveying.Com](http://www.BerrySurveying.Com)

### Test Hole #7

0-3" 10YR 2/2, Very Dark Brown, Fine Sandy Loam, Granular, Friable, Duff  
3-20" 10YR 4/6, Dark Yellowish Brown, Fine Sandy Loam, Granular, Friable, Few Roots @ 18"  
20-69" 2.5Y 5/2, Grayish Brown, Fine Sandy Loam, Fine-Med Blocky, Firm in Hole, Friable in Hand, Redox @ 20", Con & Dep 5%  
Few Stones Throughout

ESHWI @ 20"  
Terminated @ 69"  
No Ledge  
No GW  
Roots @ 18"  
PERC= 8MIN/IN

### Test Hole #8

0-4" 10YR 2/2, Very Dark Brown, Fine Sandy Loam, Granular, Friable, Duff  
4-16" 10YR 4/6, Dark Yellowish Brown, Fine Sandy Loam, Granular, Friable  
16-30" 10YR 5/8, Yellowish Brown, Fine Med Sand, Granular, Friable, Few Roots @ 20"  
30-50" 2.5Y 5/2, Grayish Brown, Fine Sandy Loam, Granular, Firm in Hole, Friable in Hand, Redox @ 30", Con & Dep 5%

ESHWI @ 30"  
Terminated @ 50"  
Ledge @ 50"  
No GW  
Roots @ 20"  
PERC= 8MIN/IN

**RECEIVED**

DEC 14 2016

TOWN OF BARRINGTON, NH  
PLANNING BOARD



### BERRY SURVEYING & ENGINEERING

335 Second Crown Pt. Rd., Barrington, NH 03825  
(603) 332-2863 / (603) 335-4623 FAX  
[www.BerrySurveying.Com](http://www.BerrySurveying.Com)



### Test Hole # 9

0-3" 10YR 2/2, Very Dark Brown, Fine Sandy Loam, Granular, Friable, Duff  
4-29" 10YR 5/6, Yellowish Brown, Fine Sand, Granular, Weak Friable, Few Roots @ 24"  
29-54" 10YR 5/6, Yellowish Brown, Fine Sand, Fine Blocky, Somewhat Firm in Hole, Friable in Hand, Redox @ 32", Con 10% No Dep

ESHW @ 29"  
Terminated @ 54"  
Ledge @ 54"  
No GW  
Roots @ 24"  
PERC= 8MIN/IN

### Test Hole #10

0-2" 10YR 2/2, Very Dark Brown, Fine Sandy Loam, Granular, Friable, Duff  
2-18" 10YR 5/6, Yellowish Brown, Fine Sandy Loam, Granular, Friable  
18-61" 2.5Y 5/3, Light Olive Brown, Fine Sandy Loam, Fine Blocky, Very Firm in Hole, Friable in Hand, No Redox

ESHW @ 18"  
Terminated @ 61"  
No Ledge  
No GW  
Roots @ 18"  
PERC= 8MIN/IN

**RECEIVED**

DEC 14 2016

TOWN OF BARRINGTON, NH  
PLANNING BOARD



### BERRY SURVEYING & ENGINEERING

335 Second Crown Pt. Rd., Barrington, NH 03825  
(603) 332-2863 / (603) 335-4623 FAX  
[www.BerrySurveying.Com](http://www.BerrySurveying.Com)

## Test Hole #11

0-2" 10YR 2/2, Very Dark Brown, Fine Sandy Loam, Granular, Friable, Duff  
2-17" 10YR 5/8, Yellowish Brown, Fine Sandy Loam, Granular, Friable  
17-64" 2.5Y 6/2, Light Brownish Gray, Fine Sandy Loam, Fine Blocky, Very Firm in Hole, Friable in Hand, Few Roots @ 17" Redox @ 21", Con & Dep 5% Stones Throughout

ESHWT @ 17"  
Terminated @ 64"  
No Ledge  
No GW  
Roots @ 17"  
PERC= 8MIN/IN

**RECEIVED**

DEC 14 2016

TOWN OF BARRINGTON, NH  
PLANNING BOARD



## **BERRY SURVEYING & ENGINEERING**

335 Second Crown Pt. Rd., Barrington, NH 03825  
(603) 332-2863 / (603) 335-4623 FAX  
[www.BerrySurveying.Com](http://www.BerrySurveying.Com)